

Declaration of Absence of Plasticizers – Rubber Roof Support SFR400 for PVshelter

Conduct Technical Solutions B.V. hereby declares that the **rubber roof support SFR400**, used with the **PVshelter**, has been tested for the absence of specific phthalates (plasticizers).

The test was conducted by **Centre Testing International Group Co., Ltd. (CTI)**. The tested component is described in the official test report as **“Rubber feet with rail SFR400”**.

The rubber roof support was tested for the following phthalates:

- Dibutyl phthalate (DBP)
- Butyl benzyl phthalate (BBP)
- Di-(2-ethylhexyl) phthalate (DEHP)
- Di-n-octyl phthalate (DNOP)
- Diisononyl phthalate (DINP)
- Diisodecyl phthalate (DIDP)

Tested Item(s)	Result	MDL
	001	
Phthalates		
Dibutyl phthalate (DBP) CAS#:84-74-2	N.D.	30 mg/kg
Butyl benzyl phthalate (BBP) CAS#:85-68-7	N.D.	30 mg/kg
Di-(2-ethylhexyl) phthalate (DEHP) CAS#:117-81-7	N.D.	30 mg/kg
Di-n-octyl phthalate (DNOP) CAS#:117-84-0	N.D.	30 mg/kg
Di-isononyl phthalate (DINP) CAS#:28553-12-0, 68515-48-0	N.D.	50 mg/kg
Di-iso-decyl phthalate (DIDP) CAS#:26761-40-0, 68515-49-1	N.D.	50 mg/kg

Remark:

- MDL = Method Detection Limit
- N.D. = Not Detected (<MDL)
- mg/kg = ppm = parts per million

For all substances tested, the result was N.D. (Not Detected). This means that these substances were not detected above the detection limit of the test method used.

This declaration is based on the official CTI test report:

Report number: A2260641885105

Tested component: Rubber feet with rail SFR400

Application: Rubber roof support for PVshelter